

FIG. I







FIG. 2

2/11




ij
Q
4
W
IJ
m
N
3
j
522
= c=
ļrē eļe
•
ļ.
r r





unused krlock_chdr_t unused krlock_chdr_t cpuspin locations cpuspin locations Quad O portion of cluster Quad O portion of cluster unused krlock_chdr_t unused krlock_chdr_t cpuspin locations cpuspin locations Quad 1 portion of cluster Quad 1 portion of cluster unused krlock_chdr_t unused krlock_chdr_t cpuspin locations cpuspin locations Quad 2 portion of cluster Quad 2 portion of cluster

FIG. 5B






FIG. 6B




FIG. 7A




FIG. 7B



cp_krlock




FIG. 8




FIG. 9 (PRIOR ART)